





Unmarked tolerance ±0.3



Pin No	Symbol	Pin No	Symbol
1	NC	10	DB7
2	NC	11	RS
3	DB0	12	R/W
4	DB1	13	E
5	DB2	14	VSS
6	DB3	15	VDD
7	DB4	16	CS
8	DB5	17	NC
9	DB6	18	NC